

INVALID PROCEDURE CODES Effective October 1, 2009

The final addendum which describes all changes to the procedure part of ICD-9-CM is posted on CMS' webpage at: <http://www.cms.hhs.gov/ICD9ProviderDiagnosticCodes>.

There were no invalid procedure codes.

NEW PROCEDURE CODES Effective October 1, 2009

The final addendum which describes all changes to the procedure part of ICD-9-CM is posted on CMS' webpage at: www.cms.hhs.gov/ICD9ProviderDiagnosticCodes

Procedure Code	Description
17.51	Implantation of rechargeable cardiac contractility modulation [CCM], total system
17.52	Implantation or replacement of cardiac contractility modulation [CCM] rechargeable pulse generator only
17.61	Laser interstitial thermal therapy [LITT] of lesion or tissue of brain under guidance
17.62	Laser interstitial thermal therapy [LITT] of lesion or tissue of head and neck under guidance
17.63	Laser interstitial thermal therapy [LITT] of lesion or tissue of liver under guidance
17.69	Laser interstitial thermal therapy [LITT] of lesion or tissue of other and unspecified site under guidance
17.70*	Intravenous infusion of clofarabine
33.73	Endoscopic insertion or replacement of bronchial valve(s), multiple lobes
38.24*	Intravascular imaging of coronary vessel(s) by optical coherence tomography [OCT]
38.25*	Intravascular imaging of non-coronary vessel(s) by optical coherence tomography [OCT]
39.75	Endovascular embolization or occlusion of vessel(s) of head or neck using bare coils
39.76	Endovascular embolization or occlusion of vessel(s) of head or neck using bioactive coils
46.86	Endoscopic insertion of colonic stent(s)
46.87	Other insertion of colonic stent(s)

Notes:

* These procedure codes were discussed at the March 11-12, 2009 ICD-9-CM Coordination and Maintenance Committee meeting and were not finalized in time to include in the proposed rule. However, they will be implemented on October 1, 2009.

REVISED PROCEDURE CODE TITLES
Effective October 1, 2009

The final addendum which describes all changes to the procedure part of ICD-9-CM is posted on CMS' webpage at: www.cms.hhs.gov/ICD9ProviderDiagnosticCodes

Procedure Code	Description
00.56	Insertion or replacement of implantable pressure sensor (lead) for intracardiac or great vessel hemodynamic monitoring
00.57*	Implantation or replacement of subcutaneous device for intracardiac or great vessel hemodynamic monitoring
33.71	Endoscopic insertion or replacement of bronchial valve(s), single lobe
39.72	Endovascular embolization or occlusion of head and neck vessels
39.79	Other endovascular procedures on other vessels
39.90*	Insertion of non-drug-eluting peripheral (non-coronary) vessel stent(s)
80.00	Arthrotomy for removal of prosthesis without replacement, unspecified site
80.01	Arthrotomy for removal of prosthesis without replacement, shoulder
80.02	Arthrotomy for removal of prosthesis without replacement, elbow
80.03	Arthrotomy for removal of prosthesis without replacement, wrist
80.04	Arthrotomy for removal of prosthesis without replacement, hand and finger
80.05	Arthrotomy for removal of prosthesis without replacement, hip
80.06	Arthrotomy for removal of prosthesis without replacement, knee
80.07	Arthrotomy for removal of prosthesis without replacement, ankle
80.08	Arthrotomy for removal of prosthesis without replacement, foot and toe
80.09	Arthrotomy for removal of prosthesis without replacement, other specified sites

Notes:

* These procedure codes were discussed at the March 11-12, 2009 ICD-9-CM Coordination and Maintenance Committee meeting and were not finalized in time to include in the proposed rule. However, they will be implemented on October 1, 2009.